


FIG. 6



-	,				
	Pos	Belt Position	Gross Empty Weight	Gross Full Weight	Material Net Weight
		P1	20	85	65
		P2	23	82	29
		РЗ	18	87	69
		P4	19	06	71
		P5	21	88	29

FIG. 8